Rack Adapter Panel

GRA-459

Assembly Manual

GW INSTEK PART NO. 82RA-45900M01

This assembly manual contains proprietary information, which is protected by copyrights. All rights are reserved. No part of this manual may be photocopied, reproduced or translated to another language without prior written consent of Good Will company.

The information in this manual was correct at the time of printing. However, Good Will continues to improve products and reserves the rights to change specification, equipment, and maintenance procedures at any time without notice.

Good Will Instrument Co., Ltd.
No. 7-1, Jhongsing Rd., Tucheng Dist., New Taipei City 236, Taiwan.




ISO-9001 CERTIFIED MANUFACTURER

GRA-459

The GRA-459 rack mount is suited for the LCR-7000 Precision LCR Meter.

Rack Mount Adapter Component List and Assembly

Description Please check and make sure all the components of the GRA-459 rack mount kit are provided.




GRA-459 Assembly

Item	Part NO.	Description	QTY
1	593B-03008NS1	SCREW FMS, 3*8*0.5m/m, ISO, N, RoHS	8
2	62RA-459LO101	*CA GRA-459 BOTTOM COVER, RoHS	1
3	62RA-459UP101	*CA GRA-459 TOP COVER, RoHS	1

Assembly


Initial setup

1. Remove the parts described below from the underside of the LCR-7000 Meter unit.
   - Foot * 4
   - Screw * 4




Installation process


1. Put the LCR-7000 Meter unit on top of the Bottom Cover (②.62RA-459LO101) followed by fastening the four FMS 3*8 screws (①. 593B-03008NS1) from the underside as the figure shown below.



2. Further assemble the Top Cover (③.62RA-459UP101) with the LCR-7000 Meter unit and fix another four FMS 3*8 screws (①. 593B-03008NS1) to the left and right flanks as the figure shown below.




3. The GRA-459 rack mount is perfectly assembled with LCR-7000 Meter unit in place.



Specification

Rack Dimensions



Unit: mm